



Cannonsville Dam Incident Response and Resolution

Thomas Murphy, P.E.
Chief, Reservoir Releases Policy Development
NYC DEP Bureau of Water Supply

December 3, 2015

Delaware River Basin Commission: Regulated Flow Advisory Committee

Agenda

- Dam
- What happened
- Immediate actions taken
- Corrective actions
- Testing the Repair
- Monitoring the Repair



Cannonsville Dam

- Completion date: 1964
- Reservoir is contained by a earthen dam with impervious clay core and a split-level spillway
- Classified as a Class “C” High-Hazard Dam per NYSDEC regulations
- The **Cannonsville Reservoir** has a 455 sq mi drainage area and a 7.5 sq mi surface area holding 97 billion gallons of water
- **Cannonsville Dam:**
 - Dam length: 2800 ft
 - Width at base 1100 ft
 - Dam height: 170 ft
- **Spillway:**
 - Located on north side of Dam
 - Spillway length & elevation:
Upper Weir: 560 ft @ 1158 ft ele
Lower Weir: 240 ft @ 1150 ft ele
- **Outlet Works**
 - 12 ft diameter pipe into
5 discharge pipes
 - ~1500 cfs – max discharge rate



What happened



Turbid Discharge 7-13-15




Immediate Actions Taken

- Site monitoring
 - 24/7 physical monitoring presence
 - Enhanced piezometer data collection/analysis by consultant experts
 - Turbidity monitoring, water sample analysis and comparison to boring samples
 - Piezometer and turbidity alarms
 - Engineer daily inspections
 - Frequent DEP Police patrols
 - Downstream flow monitoring
 - Turbid discharge plume photographic monitoring
- Review of historical information
- Stockpiling materials and equipment for emergency on-call repairs
- Consultations with FERC, DEC Dam Safety and construction contractors for repair plans
- Lowering Reservoir – maximized drinking water diversions and river releases
- Public awareness, EAP reviews, Updates with State and County OEMs



Corrective Action - Step 1

- DEP procured Moretrench as repair contractor
- Installed 8 upstream relief wells to allow artesian water through screens into casing
- Relief wells stopped the turbid discharge




Turbid Discharge Ended 8-2-15



Corrective Action - Step 2

- Compaction grouting
 - drilling to a prescribed depth
 - pumping low mobility grout through drill casing to the bottom
 - pumping continues until a safe pressure or volume limit is achieved
 - pressure and volume limits change with depth based on the geology at the borehole
 - drill casing is then pulled up 2 feet and the process is repeated



Testing the Repair (8-26-15 to 9-11-15)

- Reduced relief well pumping in a staged manner from 8-26-15 to 8-28-15
- Continue normal drinking water diversions and FFMP releases
- Continue with 24/7 site monitoring plan
- Continue turbidimeter readings and piezometer monitoring
- Continue water quality sampling and analysis



Monitoring the Repair

- September 12 to November 25, 2015
 - Continue normal drinking water diversions and FFMP releases
 - Continue turbidimeter readings and dam piezometer monitoring
 - 24/7 closed-circuit television camera feed to WSCC
 - Daily on-site documented observations by a professional engineer
 - Winterize relief wells
- November 26, 2015 through refill
 - Continue normal drinking water diversions and FFMP releases
 - Continue turbidimeter readings
 - 24/7 closed-circuit television camera feed to WSCC
 - Perform on-site documented observations and piezometer analysis by a professional engineer at least twice a week

