Field Assessment Form

New Jersey Community Development-Disaster Recovery Block Grant (CDBG-DR) Hurricane Sandy Disaster Recovery Program



Applicant ID: SRP0043579	
PAMS Pin: 1350_74_4	DCA Grant Number: B-13-DS-34-0001
Applicant Name: KATHLEEN LESBIREL	Inspection Date: 2/28/2014
Damage Address: 1229 Florence Ave, Union Beach	Inspector: Steven Rozek
Program Type: LRRP	Project Description: Rehabilitation and Elevation Within Allowable Footprint
Location Verified By: Address on house	Parcel Status: Structure exists

General Property Conditions:

Was the property accessible? Yes

Any general safety conditions or hazards noted? None

Was the building occupied at time of visit? Yes

Is there a City posting indicating property is condemned? No

Environmental Observations:

Are there any signs the property is or was previously used for commercial or industrial purposes? No

Comments:

Are there any 55-gallon metal drums visible on site or adjacent parcel? No Comments:

If drums are present, what is the use of drum on site or on adjacent parcel? N/A

If drums are present, are the drums labeled? (Take photo of label when possible) No Comments:

Are there signs of underground storage tanks or faulty septic systems on the parcel or adjacent parcel(s)? Yes

Comments: Yes, potential UST; possible vent of fill cap observed.

Are UST vents or caps present? If yes state specific location in relation to house or lot. Yes Comments: possible vent or fill cap located on rear of building by gas meter.

If UST vents or caps are present, state material(s) made from and diameter. metal 3 inch Comments:

Environmental Observations:

If UST vents or caps are present, do they appear to lead into the basement instead of underground? Yes

Comments: penetrate exterior wall

If possible UST is persent, speak to or call applicant and ask them if they can provide any details.

Comments:

Are there any other signs of chemical or industrial hazards? No

Comments:

Are there any signs of ground water monitoring or injection wells? No

Comments:

Is there a debris pile on the parcel or adjacent parcels? No

Comments:

Were any unusual objects observed? No

Comments:

Is there distressed vegetation on the parcel or adjacent parcels? No

Comments:

Is there 'above de minimis' soil staining on the parcel or adjacent parcels? No

Comments:

Were any pungent, foul or noxious odors detected? No

Comments:

Were AST's observed on the subject parcel? No

Comments:

Will the project increase the number of residential units on the parcel? If No then AST's are exempt from review. No

Comments:

If units will increase, were any AST's observed in the immediately surrounding area?

Comments:

Were wetlands observed? Yes

Comments:

If Present, how far is wetland from home? (Describe location relative to the applicant's property)

Comments: <50' west of property

Are there any obvious signs of relevant Threatened or Endangered Species? No

Comments:

Steven Rozek

2/28/2014

Site Inspector Signature

Date





1350_74_4_EA_Address_1

1350_74_4_EA_Front_1







1350_74_4_EA_Rear_2

