	Table 2. Inventory of Infalls									
Infall ID	Location (Where)	Nearest Road	Municipality	County	Note (What)	Category	Photo #			
1	Infall just downstream of pedestrian bridge ~MP 49.47	Weston Canal Road	Franklin	Somerset	Infall just north of ped. Bridge 6/4/03 - Infall not visible after heavy rain 6/6/03 - Infall flowing 2 days after heavy rain	Headwall/ Pipe	4/16/03: Canal 35 6/6/03: Canal 100			
2	Between Infalls 44 and 45 ~MP 49.13	Weston Canal Road	Franklin	Somerset						
	In front of PSEG main building, by sign MP 50.14	Weston Canal Road	Franklin	Somerset	Infall, concrete pipe just above water line 6/4/03 - Infall not visible after heavy rain 6/6/03 - Flowing 2 days after heavy rain Reutters: 18" drain, see map	Headwall/ Pipe	4/16/03: Canal 38 6/6/03: Canal 105			
	North end of Ramada, just b/f 287S ramp ~MP 50.55	Weston Canal Road	Franklin	Somerset	Small pipe Headwall, ~3-4 ft. above water line Reutters: 18" drain by 287, 1st ramp? See map	Headwall/ Pipe	4/16/03: Canal 39 6/6/03: Canal 106, Canal 107			
	Adjacent to 287 exit ramp, just before overpass MP 50.61	Weston Canal Road	Franklin	Somerset	Large headwall, partially below water line 6/6/03 - Outlet partly in water 2 days after heavy rain Reutters: 48" drain by 287	Headwall/ Pipe	4/16/03: Canal 40 6/6/03: Canal 108			
	At light just north of 287 overpass MP 50.71	Weston Canal Road	Franklin	Somerset	Headwall, sediment built up in outlet, old boom around area 6/6/03 - Flowing, 2 days after heavy rain Reutters: 15" drain, see map	Headwall/ Pipe	4/16/03: Canal 41 6/6/03: Canal 109, Canal 110, Canal 111			
	Near res. Build., by Edgewood/Route 610E MP 50.78	Weston Canal Road	S. Bound Brook	Somerset	Metal pipe in bank 6/6/03 - flowing 2 days after heavy rain	Headwall/ Pipe	4/16/03: Canal 42 6/6/03: Canal 112, Canal 113, Canal 114			
8	Sanders Ave., res. Build MP 50.87	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe in bank, ~12 feet up Few feet in from road, directly across from road sign 8/19/03 - No flow, ~2-3 days after rain Reutters: 15" drain	Headwall/ Pipe	4/16/03: Canal 43 8/19/03: Canal 117			
9	Howard Ave. MP 50.93	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe in bank, ~10-12 ft. up 8/19/03 - No flow, ~2-3 days after rain Reutters: 15" drain	Headwall/ Pipe	4/16/03: Canal 44, Canal 45 8/19/03: Canal 118, Canal 119, Canal 120			
10	By Jerome Ave., Approx. 4 ft. in from road to left of barkless tree MP 51.00	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe ~20 ft. up 8/19/03 - No flow, ~2-3 days after rain Reutters: 15" drain	Headwall/ Pipe	4/28/03: Canal 51 8/19/03: Canal 121, Canal 122			
	Upstream side of Riverside Pub, Louis Ave. MP 51.06	Weston Canal Road	S. Bound Brook	Somerset	Broken concrete pipe	Headwall/ Pipe	4/28/03: Canal 50 8/28/03: Canal 262, Canal 263, Canal 264,			

	Table 2. Inventory of Infalls									
							Canal 265, Canal 266, Canal 267			
12	Equator Ave., downstream side of Riverside Pub MP 51.10	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe ~10-15 feet back from edge, trees in front of pipe 9/19/03 - No flow, ~2-3 days after rain Reutters: 15" drain, just after spillway, 20' from water edge	Headwall/ Pipe	4/28/03: Canal 49 9/19/03: Canal 123, Canal 124, Canal 125, Canal 126			
13	Van Sickle Blvd. MP 51.23	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe few feet above water line 6/5/03 - Flow from infall after heavy rain 8/19/03 - No flow, ~2-3 days after rain	Headwall/ Pipe	4/28/03: Canal 48 6/5/03: Canal 94 8/19/03: Canal 127, Canal 128 8/28/03: Canal 259, Canal 260, Canal 261			
14	Alexander MP 51.35	Weston Canal Road	S. Bound Brook	Somerset	Concrete pipe just above water line 6/5/03 - pipe not visible after heavy rain 8/19/03 No flow, ~2-3 days after rain Reutters: 15" drain	Headwall/ Pipe	4/28/03: Canal 47 8/19/03: Canal 129, Canal 130			
15	By post office, Madison St. MP 51.40	Weston Canal Road	S. Bound Brook	Somerset	Pipe just above water line, no visible flow after heavy rain, roadwork on WCR above in June 8/19/03 - New pipe, Little flow, ~2-3 days after rain Reutters: 18" drain, just before lock	Headwall/ Pipe	4/28/03: Canal 46 6/5/03: Canal 92 8/19/03: Canal 131, Canal 132, Canal 133			
16	North side of lock by post office MP 51.52	Weston Canal Road	S. Bound Brook	Somerset	Pipe, ~10-12 ft. back from edge 8/19/03 - Little flow, ~2-3 days after rain Reutters: 2 road drains, 18", 16" drains enter ditch	Headwall/ Pipe	4/28/03: Canal 52 8/19/03: Canal 134, Canal 135, Canal 136, Canal 137, Canal 138			
17	GAF site, downstream end MP 51.67		S. Bound Brook	Somerset	Appears to be large pipe from under site Reutters: 12" drain, GAF 11/6/03: Rain last night, misty AM, rain PM, Pipe mostly submerged, milky discharge	Headwall/ Pipe	4/28/03: Canal 54 11/6/03: Canal 318, Canal 319, Canal 320, Canal 323, Canal 324			
18	GAF site upstream end (combined with 17 for modeling)	Main Street	S. Bound Brook	Somerset	2 small pipes in retaining wall 6/5/03 - no flow from pipes after heavy rain Reutters: 2-8" drains, GAF 11/6/03: Rain last night, misty AM, rain PM, Flow from 1 of the pipes	Headwall/ Pipe	4/28/03: Canal 53 11/6/03: Canal 321, Canal 322, Canal 325, Canal 326, Canal 327			
19	Behind taupe building (private property, no GPS) ~P 51.87		S. Bound Brook	Somerset	Concrete pipe, ~15 ft. back, ~10 ft. above waterline 6/5/03 - Infall not visible after heavy rain, could be covered with vegetation, but didn't see or hear flow Behind Allied Supply Building, inaccessible from road due to private property Next to municipal garage (blue building)? Reutters: 12" drain from Allied Roofers	Headwall/Pi pe	4/28/03: Canal 55			

	Table 2. Inventory of Infalls										
					detention pond						
							4/21/03: Canal 56				
	Between Brook Terrace apartment				Headwall ~8-10 ft. back from bank		8/21/03: Canal 144,				
20	complex and Staats House MP 52.3	Canal St.?	S. Bound Brook	Somerset	Some sediment, pipe needs repair 8/21/03 - No flow ~ 3-4 days after rain	Headwall/ Pipe	Canal 145, Canal 146, Canal 147, Canal 148				
20	MP 52.3	Canal St.?	DIOOK	Somerset	6/21/03 - No now ~ 3-4 days alter fain	Ріре	4/28/03: Canal 57				
					Large headwall by residential area,		6/5/03: Canal 91				
					downstream of sandbar, island		9/30/03: Canal 271,				
	End of Barber Boulevard	Barber	S. Bound		6/5/03 - After heavy rain	Headwall/	Canal 272, Canal 273,				
21	MP 52.37	Boulevard	Brook	Somerset	Reutters: past RR bridge, by Warren	Pipe	Canal 274				
	Just past gas pipeline, just before										
	Davidson light, by lawn (no GPS -	Easton				Headwall/	5/14/03: Canal 58,				
22	couldn't find)	Avenue	Franklin Twp.	Somerset	Small, broken metal pipe @ water line	Pipe	Canal 59				
23	See Infall 96										
					~2-3 foot concrete pipe just above water line						
	By Davidson Ave. light	Easton			8/21/03 - Flow, ~4 days since rain	Headwall/	8/21/03: Canal 157,				
24	MP 52.91	Avenue	Franklin Twp.	Somerset	Reutters: 15" drain by Davidson	Pipe	Canal 158				
							5/14/03: Canal 62 8/21/03: Canal 151,				
					Buried headwall, mostly filled with sediment, no		Canal 152, Canal 153,				
	~10 feet to right of Infall 24	Easton			flow	Headwall/	Canal 154, Canal 155,				
25	MP 52.91	Avenue	Franklin Twp.	Somerset	Reutters: 15" drain by Davidson	Pipe	Canal 156				
							5/14/03: Canal 63				
	Between 2 construction points b/f 287,				Lorge beedwell pertially below water line		8/21/03: Canal 159,				
	b/f lock AKA Infall 98	Easton			Large headwall partially below water line Sediment not too bad	Headwall/	Canal 160, Canal 161, Canal 162, Canal 163				
26	MP 53.11	Avenue	Franklin Twp.	Somerset	Reutters: 48" drain, see map	Pipe	8/22/03: Canal 204				
			1		Front of headwall is separated from pipe		5/14/03: Canal 64				
					Part of headwall, no pipe, ~10-15 feet up on		8/22/03: Canal 197,				
27	Just upstream of lock MP 53.23	Easton	Franklin Twp.	Somoroot	bank, channel down slope, flow - wet channel Reutters: 18" drain @ end of lock	Headwall/	Canal 198, Canal 199,				
21	IVIF 53.23	Avenue	Franklin TWP.	Somerset	Reullers. 18 drain @ end of lock	Pipe	Canal 200, Canal 201 5/30/03: Canal 65,				
	Downstream side of spillway						Canal 66				
	construction	Easton			Concrete headwall ~15 ft. up bank, flowing ~5	Headwall	8/22/03: Canal 192,				
28	MP 53.36	Avenue	Franklin Twp.	Somerset	days after rain	/Pipe	Canal 193, Canal 194				

	Table 2. Inventory of Infalls										
29	World's Fair intersection MP 53.51	Easton & World's Fair	Franklin Twp.	Somerset	Concrete headwall & pipe, 3-4 ft. diameter 5/30/03 - heavy flow 8/22/03 - Flow ~ 1 week since rain Reutters: 4 ft drain	Headwall/	5/30/03: Canal 67 8/28/03: Canal 268, Canal 269, Canal 270				
30		Easton Avenue	Franklin Twp.	Somerset	~2-3 ft. diameter, ~10 ft. up bank 5/30 and 8/22 - Flowing Reutters: 30" drain	Headwall/	5/30/03: Canal 68, Canal 69 8/22/03: Canal 190, Canal 191				
31		Easton Avenue	Franklin Twp.	Somerset	Concrete pipe, ~5 ft. up bank, no flow, bank cut in below pipe		5/30/03: Canal 70				
32	Cedar Grove Brook MP 53.80	Easton Avenue	Franklin Twp.	Somerset	Cedar Grove Brook		5/30/03: Canal 32 8/22/03: Canal 187				
33	White house to left of pipe, some grass b/w road & house, by 2 billboards on Easton MP 54.07	Easton	Franklin Twp.	Somerset	Concrete pipe ~3-4 ft. diameter, ~12-15 ft. up bank 5/30/03: flow 11/6/03: Rain last night, misty AM, rain PM, flow		5/30/03: Canal 73, Canal 74 11/6/03: Canal 305, Canal 306, Canal 307, Canal 308, Canal 309, Canal 310				
34	See Infall 61										
35	······································	Ave./Willow	Franklin Twp.	Somerset	Drainage way where enters Canal (Canal 220, 221, 222, 223) Outfall on Easton (Canal 75, 228, 229, 230, 231) 5/30: Can hear flow, can't see pipe or flow 6/2: Can see flow, still can't see pipe	Headwall to drainage	6/2/03: Canal 75 8/26/03: Canal 220, Canal 221, Canal 223, Canal 228, Canal 229, Canal 230, Canal 231				
36	Across from Hollywood Avenue By little wooden bridge, upstream of Rutgers Prep MP 54.47	Easton/Hollyw	Franklin Twp.	Somerset	6/2/03 - From towpath, See and hear flow, but no pipe, might be a stream Stream/drainage way, some sediment (Canal 216, 217, 218, 219) Outfall on Easton (Canal 232)	Headwall to drainage	6/2/03: Canal 76, Canal 77 8/26/03: Canal 215, Canal 216, Canal 217, Canal 218, Canal 219, Canal 232				
37		Easton Avenue	Franklin Twp.		~6-8 inch pipe, ~1-2 ft. above water line 6/2/03: no flow 11/6/03: Rain last night; misty AM, rain PM today, no flow when arrived, then started flowing	Headwall/	6/2/03: Canal 78 11/6/03: Canal 300, Canal 301, Canal 302				

	Table 2. Inventory of Infalls									
	Adjacent to RPS fields and through property Just upstream of cobble spillway AKA Infall 63 MP 54.73	Easton Avenue		Somerset	Large pipe draining Rutgers Preparatory School and adjoining area on Easton Avenue, Outfall at entrance to Rutgers Prep Infall 38: Outfall to Canal, large pipe Infall 63: Headwall to drainageway through campus to 138 Pipe draining RPS (211, 212, 213, 214), Outfall (233), Drainageway (234, 235), Pipe into drainageway, ~30 feet from outfall (236), Outfall into drainageway (237), Drainway to	Headwall (I63) to drainagewa	6/2/03: Canal 79 8/26/03: Canal 210, Canal 211, Canal 213, Canal 214, Canal 233, Canal 234, Canal 235, Canal 236, Canal 237, Canal 238, Canal 239, Canal 240 11/6/03: Canal 303, Canal 304			
	By Century 21 building on opposite side of Easton, by road sign on W bound side MP 55.92	Easton Avenue	Franklin Twp.	Somerset	Outfall to drainageway, some sediment	drainage	6/2/03: Canal 83 8/27/03: Canal 241, Canal 242, Canal 243, Canal 244			
	Behind houses, by Castleton Road, by brown house AKA Infall 70 MP 56.04	Easton Avenue	Franklin Twp.		Outfall to drainageway to Canal; 40 = Canal, 70 = outfall Reutters: stream	Headwall (I70) to drainage	6/2/03: Canal 84 8/27/03: Canal 245, Canal 246, Canal 247, Canal 248, Canal 250			
	Across from Girard, adjacent to Old Lane Highwood AKA Infalls 55, 56 and 90 MP 56.37	Easton Avenue	Franklin Twp.	Somerset	Infall 41: Sediment delta at Canal Infall 55: Headwall ~2/3 up drainageway Infall 56: Small pipe from adjacent residential property Infall 90: Headwall at Easton to drainageway Between 2 residential properties, Looking downstream near Infall 56 (174), Looking downstream near Infall 56 (175), Looking downstream at 15 foot drop in drainageway (176) Infall 56: Pipe from adjacent residential property, roof drain? (177) 15 Foot drop in stream by Infall 56, upstream of Infall 55 (178), Looking downstream from Infall 56 toward Infall 55 (179), Near Infall 55 (180), Infall 55 into drainageway (181, 182, 183, 184), Sediment delta (185, 186), Looking upstream toward Infall 90 from upstream of Infall 55 (294), Infall 90: Headwall at Easton (295, 296, 297), Looking downstream from Infall 90 headwall, Deep scour hole, 3+ ft deep (298, 299)	Headwalls (190, 155 and 156) to	6/2/03: Canal 85, Canal 86 8/22/03: Canal 174, Canal 175, Canal 176, Canal 177, Canal 178, Canal 181, Canal 180, Canal 181, Canal 182, Canal 185, Canal 184, Canal 185, Canal 186 10/6/03: Canal 294, Canal 295, Canal 296, Canal 297, Canal 298, Canal 299			
42	Just before Landing Lane, by big white house (private property, no GPS)	Landing Lane/Easton Avenue	Franklin Twp.	Somerset	6-8 in. PVC pipe in bank Riverview property - private, can't access	Headwall/ Pipe	6/2/03: Canal 87			

	Table 2. Inventory of Infalls										
43	By light blue house, blue steps, shale in front gardens MP 51.29	Weston Canal Road	Franklin Twp.	Somerset	Outfall to ditch to Canal, concrete & stone pipe & headwall Reutters: 15" drain	Headwall/ Pipe	6/5/03: Canal 93 8/28/03: Canal 256, Canal 257, Canal 258				
44	Downstream side of 10-Mile house, between house & lock MP 49.13	Weston Canal Road	Franklin Twp.	Somerset	Outfall to ditch to Canal, concrete & stone pipe & headwall Reutters: 36" drain @ end of lock	Headwall to ditch	6/6/03: Canal 96, Canal 97				
45	Upstream side of pedestrian bridge MP 49.33	Weston Canal Road	Franklin	Somerset	Stream to Infall 45/Culvert 1 6/4/03 - After heavy rain	Stream (culvert)	4/16/03: Canal 34 6/4/03: Canal 88 6/6/03: Canal 98, Canal 99 6/9/03: Canal 115				
46	MP 49.61	Weston Canal Road	Franklin	Somerset	Stream flowing to Infall 46/Culvert 2 4/16/03 - After heavy rain Reutters: Drain, stream	Stream (culvert)	4/16/03: Canal 36 6/4/03: Canal 89 6/6/03: Canal 101, Canal 102				
47	Just before Randolph Road, across from grassy area, inlet on opposite side of Weston Canal, past white residential building	Weston Canal Road	Franklin Twp.	Somerset	Concrete pipe ~5 feet up bank 6/6/03 - no flow 2 days after heavy rain	Headwall/ Pipe	4/16/03: Canal 37 6/6/03: Canal 103, Canal 104				
48	Short distance past Manville causeway, adjacent to camp MP 47.06	Canal Road	Franklin Twp.	Somerset	Stream inflow	Stream	8/8/03: Canal 116				
49	Downstream of lock by post office MP 51.52	Weston Canal Road	Franklin Twp.	Somerset	To right of Infall 16 if facing them with Canal at back 8/16/03 - Little flow ~2-3 days after rain	Headwall/ Pipe	8/19/03: Canal 139, Canal 140, Canal 141, Canal 142, Canal 143				
50	Just before construction trailer (going toward Landing), after Davidson U-turn, by L lane for U-turn sign AKA Infall 99 Combined with Infall 26/98 for modeling MP 53.13	Easton Avenue	Franklin Twp.	Somerset	Adjacent to road Reutters: 18" drain just before spillway and lock	Headwall/ Pipe	8/21/03: Canal 164, Canal 165, Canal 166, Canal 167, Canal 168, Canal 169 8/22/03: Canal 202, Canal 203				
51	See Infall 97										
52	Cedar Grove Road intersection, just past Exxon MP 53.65	Easton Avenue	Franklin Twp.	Somerset	Inlet on Road Reutters: 30" drain	Headwall/ Pipe	8/22/03: Canal 188, Canal 189				
53	Under 287 overpass, downstream side MP 53.29	Easton Avenue	Franklin Twp.	Somerset	Concrete headwall with concrete channel Reutters: Under 287	Headwall/ Pipe	8/22/03: Canal 195, Canal 196				
54	Just downstream of Randolph Road	Weston Canal	Franklin	Somerset	Metal pipe in bank	Pipe					

	Table 2. Inventory of Infalls									
		Road								
60		Academy Road	Franklin Twp.	Somerset	Outfall to ditch, winds around/meanders into wetlands area No visible direct discharge to Canal; overland flow possible Some sediment	Headwall to ditch to wetlands	8/26/03: Canal 208, Canal 209			
61	Across from 2 red houses, west of Culver AKA Infall 34 MP 54.00	Easton Avenue	Franklin Twp.		Large headwall, small pipe to drainage way to Canal Appears to be some sediment in pipe, overgrown stream on opposite side of Easton Reutters: 42" drain 11/6/03: Rain last night, misty AM, rain PM, flowing, somewhat murky	Stream to headwall to	5/30/03: Canal 72 8/26/03: Canal 224, Canal 225, Canal 226, Canal 227 11/6/03: Canal 311, Canal 312, Canal 313, Canal 314, Canal 315, Canal 316, Canal 317			
62	By park area across from DeMott MP 54.81	DeMott Lane	Franklin Twp.	Somerset	Stream to ditch to wetlands	Stream /ditch				
63	See Infall 38									
70	See Infall 40									
71	Foxwood Drive MP 55.86	Easton Avenue	Franklin Twp.	Somerset	Outfall and drainage (251, 252, 253) Wetland area upstream of outfall (Canal 80, 81, 82)		6/2/03: Canal 80, Canal 81, Canal 82 8/27/03: Canal 251, Canal 252, Canal 253			
73	Near Foxwood Drive, inlet by Boston Market MP 55.80	Easton Ave.	Franklin Twp.	Somerset	Large hole, little drainageway, near beginning of wetland area	Drainage ditch	8/27/03: Canal 254, Canal 255			
81	Residential area on Highwood Rd.	Highwood Road	Franklin Twp.	Somerset	Pipe to swale?	Pipe				
82	Just upstream of RPS	Easton Avenue		Somerset	Pipe	Pipe				
83	In front of Patriot Media detention basin	Weston Canal Road	Franklin Twp.	Somerset	Ріре	Pipe				
84	Behind Allied Supply MP 51.92	Washington St. & Canal	S. Bound Brook	Somerset		Pipe				
85	Behind residences	Jackson St. & Canal St.	S. Bound Brook	Somerset		Pipe				
86	Between Infalls 47 and 83 MP 49.79	Weston Canal Road	Franklin Twp.	Somerset	discharge from Patriot Media detention basin					
92		Easton Avenue		Somerset						
93	Between Infalls 25 and 96/23	Easton Avenue	Franklin Twp.	Somerset						

	Table 2. Inventory of Infalls										
94	Between Infalls 6 and 7 Combined with Infall 7 for modeling MP 50.77	Weston Canal Road	Franklin Twp.	Somerset							
96	By seminary driveway, end of lawn area, closer to Davidson, inlet on opposite side of Easton AKA Infall 23 MP 52.87	Easton Avenue	Franklin Twp.	Somerset	Concrete headwall @ water line	Headwall/ Pipe	5/14/03: Canal 60 8/21/03: Canal 149, Canal 150				
97	Just before Davidson Light, in between Infalls 26 and 50 AKA Infall 51 MP 52.98	Easton Avenue	Franklin Twp.	Somerset	Inlet on road, outfall mostly filled with sediment	Headwall/ Pipe	8/21/03: Canal 170, Canal 172, Canal 173 8/22/03: Canal 205				
98	See Infall 26			Somerset							
99	See Infall 50 Combined with Infall 26/98 for modeling MP 53.13			Somerset							