## RETURN AND REPAIR FORM



10/28/14		10/28/14	
ate Received: 10/28/14	Date given to	o service: 10/28/14	
arrier: X FedEx UPS	USPS Shipping Method	januarie) januarie	BDAY 2DAY
roduct: 6510  X 7110  7510	861U	er: AR WE-0012	
Businessons'  general sonne;	harman Printers		
7410 Upper-half	f 9510 Sim Serial#:_ Probe Serial#		· · · · · · · · · · · · · · · · · · ·
	Warranty Exp	oires: Oct. 2016 (586	55)
Technosisch Europeansch Streenwasch	Plus Demo Screener	Trade In	
ccessories		·	
110V A/C Adapter Mouthpieces Dry Gas		rinter Ribbon 510 Top Cover	Printer Paper Carrying Case
	•	Test#:	
lepair Information:		lest#.	
	Description	Qty	Total Cost
Part Number	Description Calibration		Total Cost NC/W
Part Number 414161		Qty	· · · · · · · · · · · · · · · · · · ·
Part Number 1414161 1414166	Calibration	Qty 1	NC/W
Part Number 1414161 1414166 1808455	Calibration Labor	Qty 1 1 1	NC/W NC/W
Part Number 1414161 1414166 6808455 6808486	Calibration Labor Fuel Cell	Qty 1 1 1 1	NC/W NC/W
Part Number 4414161 4414166 6808455 6808486	Calibration Labor Fuel Cell Spacer Plates	Qty 1 1 1 1 2	NC/W NC/W NC/W
Part Number 1414161 1414166 1808455 1808486 12130 18 Paper Notes: Replaced defective	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W
Part Number 1414161 1414166 1808455 1808486 12130 18 Paper Notes: Replaced defective	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W
Part Number 1414161 1414166 5808455 6808486 12130 Repair Notes: Replaced defective	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W
Part Number 1414161 1414166 1808455 1808486 12130 Repair Notes: Replaced defective	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W
Part Number 1414161 1414166 1808455 1808486 12130 Repair Notes: Replaced defective	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W
Repair Information:  Part Number  4414161  4414166  6808455  6808486  12130  Repair Notes: Replaced defective Cermetek chip, C156 and C16  Fuel Cell = ARFJ-1052	Calibration Labor Fuel Cell Spacer Plates Cermetek Modem Chip	Qty 1 1 1 2 1	NC/W NC/W NC/W NC/W

sustxfs010\Public\Forms\return and repair form 07\_21\_2011.pdf