

RETURN AND REPAIR FORM

Customer Information

B:

S:

Company Name: Ship Bottom P.D., Ship Bottom, NJ

Date Received: 12/10/13 Date given to service: 12/10/13

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810 Serial Number: AR WF-0396
 7110 8610 Printer Serial#: AR
 7510 DT5000 Sim Serial#: DD
 7410 Upper-half 9510 Probe Serial#: DD
 7410 Whole

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
MP Cal 71	Calibration	1	
MP Labor	Labor	.5	
6808455	Fuel Cell	1	
6808486	Spacer Plates	2	

Repair Notes: Replaced fuel cell and spacer plates.
Was not able to duplicate the customers complaint of BLOWING NOT ALLOWED and changing the
leaky fuel cell helped with the purge cycle. Re-configured service channel #3 which was out of range.

Fuel Cell = AREL-1328
CAL W/QC AND OPS CHECK

Service Technician BC Date: 02/06/14