

# RETURN AND REPAIR FORM



## Customer Information

B:

S:

Company Name: (none given)

Date Received: 9-22-11 Date given to service: \_\_\_\_\_

Carrier:  FedEx  UPS  USPS Shipping Method:  GRD  3DAY  2DAY  
 NDA-PRI  NDA-STD

Product:  6510  6810  
 7110  8610  
 7510  DT5000  
 7410 Upper-half  9510  
 7410 Whole

Serial Number: AR WM-0029  
 Printer Serial#: AR  
 Sim Serial#: DD  
 Probe Serial#: DD

Warranty Expires: \_\_\_\_\_

Description:  A  B  Plus  Demo  Screener  Trade In

## Accessories

110V A/C Adapter  Regulator  Printer Ribbon  Printer Paper  
 Mouthpieces  9510 Stylus  9510 Top Cover  Carrying Case  
 Dry Gas  Other (please specify) \_\_\_\_\_

## Repair Information:

Test#: \_\_\_\_\_

Part Number	Description	Qty	Total Cost
6808455	Fuel Cell	1	N/C W
6808480	Plate	1	N/C W
MPCAL 71	Calibration	1	N/C W
Misc Part	Modem Jack	1	N/C W
MP Labor	Labor	.5	N/C W

Repair Notes: MA7110 program displayed a line busy when trying to connect to 7110 unit, the modem jack was replaced was allowed MA7110 program to connect. The capacitor a location C156 was replaced it would not give a reading on the volt meter. Replaced Fuelcell ARWJ-0016, because of leakage CAL W/O C & OPS check, Installed Fuelcell ARCH-1020.

Service Technician: [Signature] Date: 9-28-11