

# RETURN AND REPAIR FORM

# Dräger

## Customer Information

B:

S:

Company Name: Harrison P.D., Harrison, NJ

Date Received: 12/28/2015

Date given to service: 12/28/2015

Carrier: ☒ FedEx

☐ UPS

☐ USPS

Shipping Method:

☐ GRD

☐ NDA-PRI

☒ 3DAY

☐ NDA-STD

☐ 2DAY

Product:

☐ 6510

☐ 6810

☒ 7110

☐ 8610

☐ 7510

☐ DT5000

☐ 7410 Upper-half

☐ 9510

☐ 7410 Whole

Serial Number: AR XC-0083

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: \_\_\_\_\_

Description:

☐ A

☐ B

☐ Plus

☐ Demo

☐ Screener

☐ Trade In

## Accessories

☐ 110V A/C Adapter

☐ Mouthpieces

☐ Dry Gas

☐ Regulator

☐ 9510 Stylus

☐ Other (please specify) \_\_\_\_\_

☐ Printer Ribbon

☐ 9510 Top Cover

☐ Printer Paper

☐ Carrying Case

## Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
4414161	Calibration	1	NC/W
4414166	Labor	4	NC/W
6808455	Fuel Cell	1	NC/W
6808486	Spacer Plates	2	NC/W
8315075	Alcotest 7110 Motherboard	1	NC/W

Repair Notes: Replaced defective fuel cell, spacer plates, and motherboard.

Unit had a leaking fuel cell and changed the motherboard due to unit getting stuck in control check mode and this resolved the issue. Grommet was found inside the cuvette, blew out cuvette of debris.

Fuel Cell = ARHL-1454

CAL W/QC AND OPS CHECK

Service Technician BC

Date: 01/20/2016