

Rt. 1 & 9 Truck NB side looking SB. Passaic River Bridge is in the background.

BEFORE



AFTER



Rt. 1 & 9 Truck NB side looking SB closer to the Passaic Bridge.

BEFORE



AFTER



Rt. 1 & 9 Truck NB side looking SB. Entire piece.

AFTER



Rt. 1 & 9 Truck NB side looking NB. **AFTER**



Rt. 1 & 9 Truck SB side looking SB. By Hackensack Ave.

BEFORE



Rt. 1 & 9 Truck SB side looking SB. By Hackensack Ave.

AFTER



Rt. 1 & 9 Truck SB side looking NB.

BEFORE



Rt. 1 & 9 Truck SB side looking SB +/- 500 L.F. South of Hackensack Ave.

Sidewalk was shifted towards the road due to junction box.

The Town of Kearny also replaced the missing fire hydrant.

AFTER



Rt. 1 & 9 Truck SB side looking SB +/- 1000 L.F. South of Hackensack Ave.

Before




The driveway apron remove/replace was not included in the initial encumbrance.

AFTER



Rt. 1 & 9 Truck SB side looking SB +/- 200 L.F. North of Central Ave.
This length of Sidewalk was not included in the initial encumbrance.

BEFORE



AFTER



A closer view looking SB



Rt. 1 & 9 Truck SB side looking NB +/- 50 L.F. North of Central Ave.

BEFORE



AFTER



Rt. 1 & 9 Truck SB side looking SB. South of Jacobus Ave. on-ramp.

BEFORE



AFTER



Rt. 1 & 9 Truck SB side looking SB. South of Jacobus Ave. on-ramp.

Closer to the Passaic River Bridge

BEFORE



AFTER



