UST Requirements

Registration

- Insurance
- Release Response Plan
- Spill/Overfill Protection
- Monthly Inspections/Inspection Forms
- Release Detection Monitoring
- Corrosion Protection
- Contacts

Why Care about USTs?

 Can threaten <u>Groundwater</u> and thus drinking water systems.
 Can be a threat to human health.
 <u>New</u> and <u>Upgraded</u> systems can still fail.

New releases persist today.

Why Care about USTs?

- Piping and dispensers the most common sources of leaking UST systems.
- Physical and mechanical damage most common overall problem.
- Both old and young piping systems experience problems.

 Release detection detects only a small percentage of actual releases.
 40% of releases affect groundwater.

NJDEP Mission

Protect human health and environment Ensure sound UST system management Protect groundwater resources Prevent, control, remediate, and abate leaking UST systems

Regulated USTs

- All tanks <u>10%</u> or more buried containing hazardous substances.
- Hazardous Substance means Motor Fuel, waste oil, others.
- Except:
 - Residential <u>Heating Oil</u> tanks of any size,
 - Non-residential heating oil tanks <u>2,000</u> gallons or less,
 - Farm/residential tanks <u>1,100 gallons or</u> less
 - -Others

Registration

- A person who owns or operates a tank
 - Must register it with NJDEP
 - May only use the tank with a valid Registration Certificate
- Registration is not transferable.
- Information is available to the public.

Registration Certificate

 Must be displayed on-site or readily available upon inspection.

Can be denied: if

- Incomplete, inaccurate, or illegible
- -No fees paid
- –O/O fails to comply with any requirement

Can be revoked if

- False, inaccurate information
- Fails to submit questionnaire
- Fails to pay fees
- NJDEP access for inspection is denied
- Fails to comply with any requirement



STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION DIVISION OF REMEDIATION SUPPORT UNDERGROUND STORAGE TANK PROGRAM P.O. BOX 028 TRENTON, NEW JERSEY 08625-0028 Phone: (609) 633-1464



UNDERGROUND STORAGE TANK SYSTEMS REGISTRATION CERTIFICATE

| maintain the Underground Sto | rage Tank System(s) describ tate of New Jersey. This re | this registration to operate and ed below in accordance with the egistration is revocable with due pursuant to N.J.A.C. 7:14B. | Approval Date: 12/01/2004 Expiration Date: 06/30/2007 | |
|---|--|---|--|--|
| Facility ID: | Facility Contact (Operato | r): | Total Number of Tanks: | |
| 123456 | Mr. Marina SMITH (609)584-4200 | | 2 | |
| Registration Activity ID: | | | Total Capacity (Gallons): | |
| UST030001 | | | 6500 | |
| Facility Address: | | Owner: | • | |
| DEL BOCA VISTA MAI 123 GOOD VIEW LANE TRENTON, NJ 08562 | | MR. JOE CLAMBAKE DEL BOCA VISTA MARINA ING 888 HARDSHELL LANE RED BANK, NJ 08888 | 2. | |
| Approved Tanks and Products | Stored: | | | |
| TANK No. TANK CAPACITY E1 4000 E2 2500 | Unleaded Gasoline Unleaded Gasoline | | | |
| This Registration | Must Be Available fo | r Inspection at the Facilit | YATALL TIMES | |

Fees

- \$100 fee for each UST facility upon initial registration.
- Three year registration cycle.
- \$300 fee for new tank installation or substantial modification.
- \$300 fee for review of closure plan.
- \$500 fee for Site Investigation plan review.

 \$1,000 fee for initial cleanup plan review.

Registration and Billing Form

Mandatory Financial Responsibility



- 7:14B-15.2 Amount and scope of required financial responsibility
- (a) Owners and operators shall maintain financial responsibility assurance for regulated underground storage tank systems in the per-occurrence amounts as follows:
- 1. For petroleum underground storage tank systems located at petroleum marketing facilities, or facilities that handle an average of more than 10,000 gallons of petroleum per month based on annual throughput for the previous calendar year:
- \$1,000,000;
- 2. For all other petroleum underground storage tanks: \$250,000; and
- For underground storage tanks systems containing hazardous substances other than petroleum: \$1,000,000.
- (b) Owners or operators shall maintain financial responsibility assurance for regulated underground storage tank systems in the **annual aggregate** amounts as follows:
- 1. For 1 to 100 underground storage tanks: \$1,000,000; and

Release Response Plan


| F | Release Response Pl | an |
|--------------------------------------|---------------------|--------------|
| | Phone # | Contact Name |
| | | |
| NJDEP Hot Line: | 877/927-6337 | |
| Fire Department: | | |
| Local Health Department: | | |
| County Health Department: | | |
| Facility Owner/Operator: | | |
| Corrective Action Contractor: | | |
| Repair Contractor: | | |
| Other Contacts: | | |
| | | |
| | | |
| | | |
| | Procedures | |
| | rocedures | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

Spill and Overfill Prevention





Make sure the colors match the actual product type.





Overfill Alarms





Flow-Restrictor Bypass. Bad

 Never store stick in the drop tube.
 Can cause an overfill.
 Can damage overfill device.





Prevention Starts Before Delivery

Owner/operator shall ensure: -There is enough room in tank before delivery. -The Entire transfer is monitored. -No <u>Spills</u> due to overfills.



Inspection Logs

 Pre-Delivery Spill Containment Inspection Logs
 = Spill Buckets
 Should be Clean and Dry prior to a delivery

Monthly Containment Device Inspection Log

Containment Sumps - Turbine Pumps
 Piping Sumps

Should be Clean and Dry

Monthly Dispenser Pan Inspection Log

- Containment pan located under the Dispenser
- Should be Clean and Dry
- Is it Water or Fuel?

Release Detection Monitoring

Summary of Options

Common

 Automatic Tank Gauging
 Interstitial Monitoring



Less Common

- Inventory Control and Tightness Testing
- Statistical Inventory Reconciliation
- Uncommon
- Manual Tank Gauging
- Soil Vapor Monitoring
- Groundwater Monitoring

Automatic Tank Gauging



General Requirements

- Must test for leaks at least every <u>30</u> days.
- Can detect a <u>0.2</u> gph leak.
- Must be a valid, passing test.
- Is third party approved for the application.
- Must have maintenance performed per <u>Manufacturer</u> specifications.
- Must maintain last <u>500</u> months of tests for inspection.
- <u>95</u>% probability of finding a leak and <u>5</u>% of a false alarm.
- Must measure for water monthly.

Types of Reports

JUN 12, 2001 5:00 AM

INVENTORY REPORT

| T 2:UNLEADED PREMIUM VOLUME = 2671 GALS ULLAGE = 5365 GALS 90% ULLAGE = 4561 GALS TC VOLUME = 2647 GALS HEIGHT = 43.82 INCHES WATER VOL = 0 GALS WATER = 0.00 INCHES TEMP = 72.7 DEG F T 3:DIESEL VOLUME = 2696 GALS ULLAGE = 7502 GALS 90% ULLAGE = 6482 GALS TC VOLUME = 2685 GALS HEIGHT = 37.13 INCHES WATER VOL = 0 GALS WATER = 0.00 INCHES | T 1:UNLEAD VOLUME ULLAGE 90% ULLAGE TC VOLUME HEIGHT WATER VOL WATER TEMP | | REGUL 8868 3054 1861 8766 33.26 0.00 76.3 | AR GALS GALS GALS INCHES GALS INCHES DEG F |
|---|---|---------------------------------------|--|---|
| VOLUME = 2696 GALS ULLAGE = 7502 GALS 90% ULLAGE= 6482 GALS TC VOLUME = 2685 GALS HEIGHT = 37.13 INCHES WATER VOL = 0 GALS WATER = 0.00 INCHES | VOLUME ULLAGE 90% ULLAGE TC VOLUME HEIGHT WATER VOL WATER | | 2671 5365 4561 2647 43.82 0 0.00 | GALS GALS GALS INCHES GALS INCHES |
| TEMP = 69.2 DEG F | VOLUME ULLAGE 90% ULLAG TC VOLUME HEIGHT WATER VOL | = = = = = = = = = = = = = = = = = = = | 7502 6482 2685 37.13 0 | GALS GALS GALS INCHES GALS |

| 06-28-01 1:05 PM |
|---|
| |
| SYSTEM STATUS REPORT |
| T 1:LOW PRODUCT ALARM |
| T 1:DELIVERY NEEDED |
| T 2:LEAK ALARM |
| T 2:SUDDEN LOSS ALARM |
| T 3:LOW PRODUCT ALARM |
| T 3:DELIVERY NEEDED |
| INVENTORY REPORT |
| T 1:DIESEL VOLUME = 914 GALS ULLAGE = 9086 GALS 90% ULLAGE = 8086 GALS TC VOLUME = 908 GALS HEIGHT = 14.12 INCHES WATER VOL = 41 GALS |

Types of Reports

OCT 22. 1999 8:00 AM CSLD TEST RESULTS OCT 22. 1999 8:00 AM

.

T 1:DIESEL PROBE SERIAL NUM 408247

0.2 GAL/HR TEST PER: OCT 22, 1999 PASS

T 2:SUPER PROBE SERIAL NUM 408613

0.2 GAL/HR TEST PER: OCT 22, 1999 PASS

T 3:REGULAR PROBE SERIAL NUM 408244

0.2 GAL/HR TEST PER: OCT 22, 1999 PASS JAN 22. 2002 11:43 AM

LEAK TEBT REPORT

T. 3: REGULAR TANK PROBE BERIAL NUM 240331

TEBT STARTING TIME: JAN 15, 2002 11:00 PM

LEAK TEST RESULTS GROBS TEST PASS

**** F H END * * * * *

Find the Tank Gauge



Statistical Inventory Reconciliation (SIR)

 Have inventory numbers analyzed by approved vendor each month.

Pass/Fail/Inconclusive

- <u>2</u> Inconclusives = suspected release.
- Must switch to other method if the cause of the inconclusive results is not corrected.

Leak Detection for Piping

Pressurized

Or

Suction?







ALLD Makes and Models

Mechanical









Electronic

Pressure Transducer



Wireless




Mechanical ALLD Testing

- Device must be function-tested every year.
- Use licensed service provider.
- Idea is to introduce a controlled leak and see if device finds it.





Interstitial Principles



Double wall pipe with open interstice



Sump and sensor



VEEDER-ROOT

Gauge with electronic read-out

Annual Line Tightness Test

Hire a UST tightness tester. Have each pipe tested annually. Must get passing test of 0.1 gph leak rate.

 Keep copy of test results.

| as per test protocol to obtain the test results are? (Pass/Fail)* | | | |
|--|---------|-----------|------|
| | | | |
| | Line 1 | Line 2 | Line |
| (S) single wall; (D) double wall | 5 | 5 | 5 |
| (T) turbine; (S) suction | T | T | t |
| c detector present? (Yes/No) ead seal intact? (Yes/No N/A) or results? (Pass/Fail) ve located at? (T) tank (P) pump | YW PASE | Y AASS MA | Yeas |
| esults are? (in gallons per hour) | 0.0 | 0.0 | 0,0 |
| s? (Pass/Fail)* | DASS | PASS | PAS |

tanks or piping will not be considered as a valid tightness test for the purp e detection regulations.

Cathodic Protection

Requirements Sacrificial Systems - Stip3 Tanks

System must be tested 1x every 3 years Keep records on site

Impressed Systems

- System must be tested 1x every 3 years
- The Rectifier must be inspected once every 60 days.





A steel tank must have a passing Cathodic Test!

Frequent Contacts

- UST Compliance & Enforcement 609-984-5855
 - Northern Bureau, (973) 656-4099: Bergen, Essex, Hudson, Hunterdon, Morris, Passaic, Somerset, Sussex & Warren
 - Central Bureau, (609) 584-4200, Mercer, Middlesex, Monmouth, Ocean & Union
 - Southern Bureau, (856) 614-3655, Atlantic, Burlington, Camden, Cape May, Cumberland, Gloucester, & Salem
- UST Registration 292-2728 or 292 2718
 Discharge Notifications/Complaints Call DEP Hot-Line 1-877-WARN-DEP or 1-877-927-6337

Frequent Contacts cont.

- Regulated Underground Storage Tank 292-8761
- Homeowner tanks (heating oil) Case Assignment 292-2943
- Air Permits Bureau of New Source Review 292-9258
- Propane Tanks Department of Labor 292-1190
- Septic Tanks/Systems 292-0407
- ISRA/ECRA 777-0899
- Radiation 633-2210 Radon 984-5425 Radon Hot-line 800 648-0394
- Well Searches/Well Permits Bur. Of Water Allocation 292-2957

Frequent Contacts cont.

- Homeowner Well Monitoring (Private Well Testing Program) 292-5550
- Above Ground Storage Tanks
 - local construction, fire and health officials
 - If >20,000 gallons of hazardous substances on-site -DPCC 633-0610
- Applications for UST Certification/Information About a Certified Firm or Individual 777-1007
- Variances from the Tech Regs. Or Directions How To Proceed With A Site Investigation Which Has No Case Manager - Set to Case Assignment for Issuance of An MOA 292-2943

websites

www.state.nj.us/dep

www.state.nj.us/dep/srp/ust

www.state.nj.us/dep/enforce ment

John Olko Principal Environmental Specialist Central Bureau of Water Compliance and Enforcement P.O. Box 407 Trenton NJ 08625-0407 609-584-4200