

# RECALLED GENERATORS

These portable generators have been the subject of recalls due to safety hazards or other reasons.

Sources: U.S. Consumer Product Safety Commission; New Jersey Division of Consumer Affairs. Further information about product recalls: [www.cpsc.gov](http://www.cpsc.gov).

## AMERICAN HONDA GAS-POWERED GENERATORS



**Model No.** EU7000iS AT, serial numbers EEJD-100001 to EEJD 1006288  
**Recall Date:** September 10, 2014  
**Hazard:** The rear frame support can fail during lifting, posing an impact hazard. The owner's manual can have missing or duplicated pages, which could cause consumers not to receive important operating or safety information.  
**Remedy:** Consumers should immediately stop using the recalled generators and contact a Honda Power Equipment dealer to schedule a free repair of the rear frame support and replacement of the owner's manual.

[www.cpsc.gov/en/Recalls/Recall-Alerts/2014/American-Honda-Recalls-Gas-Powered-Generators/](http://www.cpsc.gov/en/Recalls/Recall-Alerts/2014/American-Honda-Recalls-Gas-Powered-Generators/)

## AMERICAN HONDA PORTABLE GENERATORS



**Model No.** EU200i, serial numbers EAAJ-2260273 through EAAJ-2485025  
**Recall Date:** November 15, 2012  
**Hazard:** The generator's fuel hose can leak, posing fire and burn hazards.  
**Remedy:** Consumers should immediately stop using the recalled generators and contact the nearest Honda Power Equipment dealer to schedule a free inspection and repair.

[www.cpsc.gov/en/Recalls/2013/American-Honda-Recalls-Portable-Generators-Due-to-Fire-and-Burn-Hazards/](http://www.cpsc.gov/en/Recalls/2013/American-Honda-Recalls-Portable-Generators-Due-to-Fire-and-Burn-Hazards/)

## AMERICAN HONDA PORTABLE GENERATOR BATTERIES

**Gen. Model No.** EM4000SX, EM5000SXX3 and EM6500SXX2 with hazard labels printed in Japanese, various serial numbers identified in CPSC alert.  
**Recall Date:** June 23, 2011  
**Hazard:** The hazard labels attached to the batteries used on the generators are printed in Japanese instead of English. As a result, consumers handling the battery may not be able to adequately avoid risks associated with the batteries.  
**Remedy:** America Honda contacted consumers and gave them the correct label. Consumers can either install the label themselves or contact a Honda dealer to install the label free of charge.

[www.cpsc.gov/en/Recalls/2011/American-Honda-Recalls-Portable-Generators/](http://www.cpsc.gov/en/Recalls/2011/American-Honda-Recalls-Portable-Generators/)

## SUBARU PORTABLE GASOLINE GENERATORS



**Model No.** Models SGX3500, SGX5000, SGX7500, various serial numbers identified in CPSC alert  
**Recall Date:** July 23, 2013  
**Hazard:** The fuel tank can leak, posing a fire or burn hazard.  
**Remedy:** Consumers should immediately stop using the generators and contact Robin America to schedule a free repair.

[www.cpsc.gov/en/Recalls/2013/Subaru-Portable-Gasoline-Generators-Recalled-by-Robin-America/](http://www.cpsc.gov/en/Recalls/2013/Subaru-Portable-Gasoline-Generators-Recalled-by-Robin-America/)

## CHAMPION POWER EQUIPMENT PORTABLE GENERATORS



**Model No.** Models 41332 and 41532, various serial numbers identified in CPSC alert  
**Recall Date:** November 2, 2012  
**Hazard:** Fuel can leak from the generator's carburetor, posing a fire hazard.  
**Remedy:** Consumers should stop using the recalled generators immediately and contact Champion Power Equipment for a free repair kit to be installed by an authorized dealer. The consumer may also return the unit to Costco for a full refund.

[www.cpsc.gov/en/Recalls/2013/Portable-Generators-Recalled-by-Champion-Power-Equipment-Due-to-Fire-Hazard-Sold-Exclusively-at-Costco/](http://www.cpsc.gov/en/Recalls/2013/Portable-Generators-Recalled-by-Champion-Power-Equipment-Due-to-Fire-Hazard-Sold-Exclusively-at-Costco/)

## POWERMATE SX5500 PORTABLE GENERATORS



**Model No.** Model name Sx550, number PM012550, serial numbers ranging from K003xxxxxQ through K090xxxxxQ  
**Recall Date:** November 13, 2012  
**Hazard:** The fuel filter on this generator allows gasoline to leak, posing a fire hazard.  
**Remedy:** Consumers should stop using these recalled portable generators and contact Pramac America to receive a free repair kit including a replacement filter, hose and hose clamps for fuel line.

[www.cpsc.gov/en/Recalls/2013/Powermate-Generators-Recall-to-Repair-by-Pramac-America-Due-to-Fire-Hazard-Sold-Exclusively-at-Home-Depot/](http://www.cpsc.gov/en/Recalls/2013/Powermate-Generators-Recall-to-Repair-by-Pramac-America-Due-to-Fire-Hazard-Sold-Exclusively-at-Home-Depot/)

## POULAN PRO GENERATORS



**Model No.** Models PP4300, PP6600, PP6600E and PP7600E, all serial numbers  
**Recall Date:** January 20, 2011  
**Hazard:** The carburetor can fail allowing gasoline to leak, posing a fire hazard to consumers.  
**Remedy:** Consumers should immediately stop using the recalled generators and contact Husqvarna to arrange a free repair.

**NOTE:** A New Jersey retailer allegedly sold these generators after their recall

[www.cpsc.gov/en/Recalls/2011/Poulan-Pro-Generators-Recalled-by-Husqvarna-Professional-Products-Due-to-Fire-Hazard/](http://www.cpsc.gov/en/Recalls/2011/Poulan-Pro-Generators-Recalled-by-Husqvarna-Professional-Products-Due-to-Fire-Hazard/)



[www.NJConsumerAffairs.gov](http://www.NJConsumerAffairs.gov) • 800-242-5846