

**William H. Cahill**

P.O. Box 62054  
Cincinnati, Ohio 45262-2054



**Custom Roof Thatch, Ltd.**

Phone (513) 772-4974  
Fax (513) 772-6313

April 16, 2013

To: NJMC

1 Dekorte Plaza

Lyndhurst, NJ 07071

Attn. Katy Wedel

To do first class repairs from storm damage to the thatch structure at the River Barge Park.

1. Carefully remove and replace the thatch on the west and east side of the gable ends on the north side.
2. Install thatch and tighten up the thatch on the east and west side gable ends at the north end of the thatch structure.
3. Dress and tighten each side of the total roof because of wind damage from the storm.
4. Repair and replace 4 feet of the ridge on the north side.
5. Clean the roof of thatch and debris.

Break down of prices:

Rental of 50 foot lift for one week	\$2300.00
Scaffold Rental	\$ 380.00
Materials and shipping	\$1200.00
Dressing and cleaning each side of the roof at \$1500.00 each side	\$3000.00
Repairs and dressing to the gable end of the roof	\$2020.00
Total cost of repairs	\$8900.00

The job will take 8-10 days weather permitting.

Call me if you have any questions.

William Cahill

513-225-0368