

# Return & Repair Form:

3955

## Customer Information:

Company Name: NJSP Avalon B: \_\_\_\_\_ S: \_\_\_\_\_  
 Date Received: 2/8/2010 Date Given to Service: \_\_\_\_\_  
 Carrier: FedEx - UPS - DHL - USPS Method: GRD NDA - 2DY - 3DY - Other

## Product Information:

Product: 7410-7110-6510-6810-7510 Serial #: AR VM-0062  
9510-Drug Tester 5000  
 Description: A - B - Plus - Screener - Demo Printer Ser #: AR -  
 Whole Instrument \_\_\_\_\_ Top 1/2 \_\_\_\_\_ Sim Ser #: \_\_\_\_\_  
 Other \_\_\_\_\_ Probe Ser # DD P -  
**ACCESSORIES:**  
 110 V A/C Adapter  Regulator  Mag Card Rdr# \_\_\_\_\_  
 Printer Paper  Printer Ribbon  Casio # \_\_\_\_\_  
 Mouthpieces  Carrying Case  Dry Gas  
 Other (Please Specify) \_\_\_\_\_ Warranty Exp. Date \_\_\_\_\_

## Repair Information:

Test #

Reason for Return:			
Part Number	Description	Qty	Total Cost
<u>6809500</u>	<u>CUVETTE</u>	<u>1</u>	<u>n/c warr</u>
<u>6809512</u>	<u>IR sensor, Bar 13</u>	<u>1</u>	<u>n/c warr</u>
<u>12014</u>	<u>Nipple</u>	<u>1</u>	<u>n/c warr</u>
<u>OP Cal 71</u>	<u>Cal</u>	<u>1</u>	<u>n/c warr</u>
<u>MT Labor</u>	<u>Labor</u>	<u>.5</u>	<u>n/c warr</u>

### Repair Notes:

Unit arrived with a Error 23 noted on paper work, but not duplicated. Unit would come ready. I check thermal fuse test OK, IRV Read 0.012V P-T Change IRV sensor unit would not give a IRV Reading Change CUVETTE's unit came ready.

Cal w/Cal; Ops check

Service Technician: JS

Date: 2/8/2010