

10497777- ~~800017526~~ 80017539



RETURN AND REPAIR FORM

Customer Information

B: 57155 S: 11

Company Name: Paulsboro NJ

Date Received: 7-21-11

Date given to service: _____

Carrier: FedEx UPS USPS Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR W1A-0183

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: _____

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
8100902	Flow Sensor	1	w/c w
mp cal 71	Calibrate	1	w/c w
mp labor	labor	1.5	N/C w

Repair Notes: Unit displayed a blowing not allowed during ABIA test, Flow sensor was changed and ABIA test was ran as well as a stand check thru the hose and no problems found. Supervisor had tech complete a series of test including 0.100, .04, .08, .4, Solw-changing Lin-test with .04, .08, 0.100, also a CTRL-TEST with 0.100. Unit also passed calibration test as well all the other tests mentioned above.

Service Technician: [Signature]

Date: 8-8-11

Turnover