

NJ

Drägersafety

Return & Repair Form

Customer Information:

CUSTOMER Clifton PD NJ Cust # 59800
 Date of Return: 7/13/07 Carrier: Fedex Method: Stand O/W

Product Information:

Product : 7110 7410 6510 6810 Serial # AR10M-0025
 Description: A B PLUS SCREENER _ Printer Serial # _____
 Whole Inst. Top Half Simulator Serial # _____
 OTHER : _____ Probe Serial # _____
 Demo Unit Returned to stock on: _____
 Accessories: (check all that apply):
 110VAC Adapter Regulator Mag Card Rdr # _____
 Printer Paper Printer Ribbon Casio # _____
 Mouthpieces Carrying Case Dry Gas
 Other (specify): _____
 Warranty Expiration Date: _____

Repair Information:

Test # _____

Reason for Return: ERROR 32 AGAIN

Part #	Description	Qty	Total
<u>6807819</u>	<u>SWITCH</u>	<u>1</u>	<u>WARR</u>
<u>6810269</u>	<u>ESCAP MOTOR</u>	<u>1</u>	<u>"</u>
<u>8100284</u>	<u>PRINT RIBBON</u>	<u>1</u>	<u>"</u>
<u>MPCAC 71</u>	<u>CAL</u>	<u>1</u>	<u>"</u>

NO CHARGES

Repair Notes: ERROR CAUSED BY RANDOM FAILURE OF SWITCH AND FAULTY MOTOR CONTACTS - REPLACED BOTH / CAL EOPS CHECKS

Technician: VE

Date: 07-19-2007