

Capoolong Creek Streambank Restoration

The photos below document aspects of the Division of Fish and Wildlife's streambank restoration project at Capoolong Creek Wildlife Management Area, located in Franklin Township, Hunterdon County. For details visit www.njfishandwildlife.com/wma_restoration-capoolong.htm.

PHOTOS:

Eroded section of Capoolong Creek, looking downstream. Bank is mostly vegetated by Japanese stiltgrass.



Eroded section of Capoolong Creek, looking upstream. The public trail can be seen in the left of the photo, as well as where erosion is threatening the trail.



Loader transporting boulders to the project site.



Restored bank, looking upstream, showing native trees ready to be planted and new pool.



Restored bank, looking downstream, with completed riparian buffer plantings.



Restored stream bed with added rock and gravel to help dissipate water energy to main channel.

