

RETURN AND REPAIR FORM



Customer Information

B:

S:

Company Name: New Jersey State Police, Hamilton, NJ

Date Received: 01/20/15

Date given to service: 01/20/15

Carrier: FedEx UPS USPS

Shipping Method: GRD 3DAY 2DAY
 NDA-PRI NDA-STD

Product: 6510 6810
 7110 8610
 7510 DT5000
 7410 Upper-half 9510
 7410 Whole

Serial Number: AR LM-0286

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: June 2015

Description: A B Plus Demo Screener Trade In

Accessories

110V A/C Adapter Regulator Printer Ribbon Printer Paper
 Mouthpieces 9510 Stylus 9510 Top Cover Carrying Case
 Dry Gas Other (please specify) _____

Repair Information:

Test#:

Part Number	Description	Qty	Total Cost
4414161	Calibration	1	NC/W
4414166	Labor	2	NC/W
6808455	Fuel Cell	1	NC/W
6808486	Spacer Plates	2	NC/W
8312928	Display	1	NC/W

Repair Notes: Replaced defective display, fuel cell, and spacer plates.

IRV which was too low causing Error 23 was adjusted and display had large dark area.

Rubber bumper was missing which was replaced.

Fuel Cell = ARFK-0618

CAL W/QC AND OPS CHECK

Service Technician BC

Date: 01/28/15