

# RETURN AND REPAIR FORM

# Dräger

## Customer Information

B:

S:

Company Name: NJSP - Hamilton Technology Center, Hamilton, NJ

Date Received: 02/14/2017

Date given to service: 02/14/2017

Carrier: ☐ FedEx ☒ UPS ☐ USPS Shipping Method: ☐ GRD ☐ 3DAY ☐ 2DAY  
☐ NDA-PRI ☒ NDA-STD

Product: ☐ 6510 ☐ 6810  
☒ 7110 ☐ 8610  
☐ 7510 ☐ DT5000  
☐ 7410 Upper-half ☐ 9510  
☐ 7410 Whole

Serial Number: AR WE-0018

Printer Serial#: AR

Sim Serial#: DD

Probe Serial#: DD

Warranty Expires: \_\_\_\_\_

Description: ☐ A ☐ B ☐ Plus ☐ Demo ☐ Screener ☐ Trade In

## Accessories

☐ 110V A/C Adapter ☐ Regulator ☐ Printer Ribbon ☐ Printer Paper  
☐ Mouthpieces ☐ 9510 Stylus ☐ 9510 Top Cover ☐ Carrying Case  
☐ Dry Gas ☐ Other (please specify) \_\_\_\_\_

## Repair Information:

Test#:

| Part Number | Description      | Qty | Total Cost |
|-------------|------------------|-----|------------|
| 4414161     | Calibration      | 1   |            |
| 4414166     | Labor            | 5   |            |
| 6808455     | Fuel Cell        | 1   |            |
| 6808374     | Geared Engine    | 1   |            |
| 8315075     | 7110 Motherboard | 1   |            |
|             |                  |     |            |
|             |                  |     |            |
|             |                  |     |            |

Repair Notes: Replaced defective fuel cell, geared engine, and motherboard.

Motherboard was changed due to giving wrong solution control amount.

Fuel Cell = ARJL-0056

CAL W/QC AND OPS CHECK

Service Technician BC

Date: 03/02/17