

Drägersafety

Internal Use Only

Return & Repair Form

Customer Information:

CUSTOMER GB Police Cust # _____
 Date of Return: 9/1/06 Carrier: Fed Ex Method: Exp. Silver

Product Information:

Product : 7110 7410 6510 6810 Serial # ARWJ-0006
 Description: A B PLUS SCREENER _ Printer Serial # _____
 Whole Inst. Top Half Simulator Serial # _____
 OTHER : _____ Probe Serial # _____

Demo Unit ☐ Returned to stock on: _____

Accessories: (check all that apply):

- ☐ 110VAC Adapter ☐ Regulator ☐ Mag Card Rdr # _____
☐ Printer Paper ☐ Printer Ribbon ☐ Casio # _____
☐ Mouthpieces ☐ Carrying Case ☐ Dry Gas
☐ Other (specify): _____

Warranty Expiration Date: _____

Repair Information:

Test # _____

Reason for Return: LOW EC Readings on SOLW-CHANGE only

Part #	Description	Qty	Total
6808455	Fuel Cell	1	
MPLAL71	7110 CAL	1	
MPLABOR	LABOR	3	

Repair Notes: EC readings confirmed low on 2nd + 3rd tests during SOLW-CHANGE ONLY. Found that F/C cause this. Replaced F/C. Cal ops check + Q.C.

Technician: CPD

Date: 9/1/06